



Index

- Aftercrazing 35
Alarm 2, 22, 24, 28
 ALAr 22, 24, 28, 39
Bisque 35
Brick repairs 34
Candling 26, 35
Ceramic 35
Clean-up 35
Clear display 31
Clicking 11
Complete
 CPLt 22, 24, 39
Cone
 ConE 21, 38, 39
 deformation 37
 heat work 38
 value 29
Cone Fire 1, 19, 31
 description 1
 profiles 1, 19, 20, 21
 programming 21, 22
Cone plaque 35
Cone Table 4, 29, 38
Cones 12
 self-supporting 12
 senior 12
Controlled cooling 26
Controller 4
 connecting
 3 phase 6, 10
 single phase 6
 kiln settings 7
 Kiln-Sitter 7
 switches 7
 timer 7
 locating 6
 mounting 6
Crackle glaze 35
Cracks in the body 33
Crazing 33, 35
 delayed or aftercrazing 33
Crystalline glaze 27
Delay 22, 25, 28
 deLA 21, 22, 24, 39
Dipping 35
Display dim 32
Dry footing 14, 35
Electrical
 chart of specifications 10, 47
 3 phase 6, 10
 voltage 10
Element
 groove 35
 replacing 35
EnviroVent 16
Error
 Err 39
 messages 40
FAIL 39
Firebrick 35
Firing 16, 35
 after the firing 16
 china paint 16
 during the firing 18
 glass 14, 18, 27
 glaze 14, 16, 27
 greenglaze 16
 lusters 17
 metallics 16
 overglaze 14, 16
 oxidation 11
 porcelain 14, 17
 stoneware 14, 17
 underglaze 16
Floor repairs 34
Foot 35
Fuse, electrical 32, 37
Glass slumping 27
Glaze 14, 18, 35
 cloudy 33
 cratered or bubbled 32
 crawled 32
 excessive 33
 grainy 33
 red
 discolored 33
 grayed 33
 sagging 32
 textured 33
Greenware 13, 35
Heat work 37
Hold 24
 HLD 39
 HLD 1-8 25, 39
 HOLD 22, 39
Impurities 35
Incising 35
Kiln-Sitter 36
Kiln wash 11, 36
KilnMaster controller 4, 35
 features 1, 4, 19, 37
 wall mount
 repairs 7
Lid repairs 34
Limit timer 36
Loading 13, 15
 glass fusing 14
 glaze 14
 greenware 13
 overglaze 13
 porcelain 13
Locating kiln 8
Lusters 17, 36
Mature 36
Multitester 36
Nesting 36

Ohm meter	36
One-fire	36
Overglaze	16, 36
discolored	33
PK-Production Kilns	45
Peephole	15, 36
Peephole plug	15, 36
Pinholes	32, 36
Porcelain	17, 27, 36
Posts,	36
Pouring,	36
Power failure, PF	22, 25, 39
Pyrometer	36
Pyrometric Cone	12, 36, 38
Ramp/Hold	1, 26, 31, 37, 38
description	24
hold	24, 39
programming	25, 26
rate	24
temperature	24
Rate	
rA	39
rA 1-6	25
Refractory	36
Repairs	34
Wall repairs	34
Floor repairs	34
Lid repairs	34
KilnMaster repairs	7
Replacing elements	35
Replacing thermocouple	7, 8, 35
Review	29
Segment	24, 29
chart	24, 29
SEGS	23, 39
Sgraffito	36
Shelf	10, 36
Shiny matte surface	33
Shut off	
early	31
Slip	36
Soaking	36
Specifications	
fuse	37
Speed	
SPd	22, 39
Stilts	14, 36
Start firing	30
Stoneware	17, 36
Stop firing	30
Talc	36
Temperature	
flashing	1, 30, 39
scale selector	28
steady	39
Terminal brick	36
Terra cotta	36
Thermocouple	7, 36, 37
flaking	32
mounting	7
replacement	7, 35
Three-phase	
operation	6, 10
Time	
decreasing	39
Troubleshooting	31
fuses	32
Underglaze	16, 33, 36
Unpacking kiln	8, 46
User profile	2, 23
USEr	2, 24, 39
Venting	15, 36
EnviroVent	15, 16
lid	15, 16
View	29
Vitreous	36
Volt meter	36
Ware	32, 36
Warpage	36
Wiring diagrams	41, 48